





On behalf of American Honda Motor Co. Inc., Rebuilders Automotive Supply (RAS) has been hired to coordinate the purchase and return of specific recalled, non-deployed airbags from salvage yards. RAS is providing this notice to you with respect to parts in the following vehicle populations.

**Vehicle Ranges Affected:**

DRIVER AIRBAG		PASSENGER AIRBAG	
Honda	Acura	Honda	Acura
2001-07 Accord	2003 CL	2003-05 Accord	2003-06 MDX
2001-05 Civic	2003-06 MDX	2008-11 Accord	2005-11 RL
2002-11 CR-V	2002-03 TL	2010-11 Crosstour	2009-11 TSX
2011-15 CR-Z	2013-16 ILX	2001-11 Civic	2010-11 ZDX
2003-11 Element	2013-14 ILX Hybrid	2002-11 CR-V	
2009-13 Fit	2007-16 RDX	2003-11 Element	
2013-14 Fit EV	2005-12 RL	2007-11 Fit	
2010-14 Insight	2009-14 TL	2010-11 Insight	
2002-04 Odyssey	2010-13 ZDX	2007-11 Odyssey	
2003-08 Pilot		2003-11 Pilot	
2006-14 Ridgeline		2006-11 Ridgeline	



As American Honda Motor Company, Inc. and NHTSA have publicly advised, in certain vehicles, the passenger and/or driver frontal airbag inflator could produce excessive internal pressure. If an affected airbag deploys, the increased internal pressure may cause the inflator to rupture. In the event of an inflator rupture, metal fragments could be propelled upward toward the windshield, or downward toward the front foot well, potentially causing injury or fatality to vehicle occupants.

**These recalled airbags SHOULD NOT be resold to the public, repair shops, service stations, or any other entity for reuse.**

**On December 4, 2015, the FAST Act, Public Law 114-94, was signed into law. Section 24110 of the FAST Act increases the maximum civil penalty that NHTSA may collect for each violation of the Vehicle Safety Act to \$21,000 per violation and the maximum amount of civil penalties that NHTSA can collect for a related series of violations to \$105 million.**

Along with each part, RAS requires the VIN of the donor vehicle. The VIN **MUST** be pre-authorized by RAS prior to receiving a purchase order and shipping documents.

Each Airbag **MUST** be individually labeled with the VIN of the donor vehicle, as the VIN information is critical in tracing the airbag to a master list of Honda and Acura vehicles affected in the recall.

Please go to [www.coresupply.com](http://www.coresupply.com) and click the **RECALL** tab to pre-qualify the VINs you have in inventory.

**\*\*\*NOT ALL VINs for the vehicles ranges listed above qualify for the recall\*\*\***

Specific shipping and labeling information will be provided at the time of VIN authorization. Both RAS and Honda appreciate your help in facilitating this collection.